

2006 REPORT OF THE GENERAL MANAGER
OCCUPATIONAL HEALTH & SAFETY ACT HEALTH CARE & RESIDENTIAL FACILITIES
LOCATION(S): NEWMARKET HEALTH CENTRE MAPLE HEALTH CENTRE

Page 1 of 3

STATUS REPORT RATING SCALE:

1 = Compliant

2 = Partially Compliant

3 = Not Compliant

4 = Not Applicable

REGULATION	COMPLIANCE STATUS	COMMENTS, ACTION TAKEN AND/OR FOLLOW-UP ACTIVITIES PLANNED
NOTICE OF ACCIDENTS SECTIONS: s. 5 (1)-(5), s.6, s.7. O. Reg. 67/93	1	Full Compliance
GENERAL DUTY TO ESTABLISH MEASURES AND PROCEDURES SECTIONS: s. 8, s.9 (1)-(4), O. Reg. 67/93	1	Full Compliance
PERSONAL PROTECTIVE EQUIPMENT SECTIONS: s. 10 (1) – (2), s. 11, s. 12, O. Reg. 67/93	1	Full Compliance
SECTIONS: s. 13 (1)-(3), O. Reg. 67/93	4	Refers to work performed at heights above 3 metres, excluding work performed from a ladder. All work of this nature is contracted to qualified firms. Contract service specifications require the contractor and his/her staff to comply with this legislation.
SECTIONS: s.14 (1)-(2), O. Reg. 67/93	4	Refers to exposures to the hazards of drowning. No workers are exposed to a drowning hazard as defined by the regulation.
SECTIONS: s. 15 (1) O. Reg. 67/93. A worker who supports or restrains a patient/resident during x-ray irradiation of the patient/resident shall be provided with and wear a protective apron and protective gloves and where appropriate, a protective collar.	1	All the required protective equipment for this service is provided by the contracted diagnostic/laboratory service.
s. 15 (2), O. Reg. 67/93. The equipment provided under subsection (1) shall have a lead equivalence of at least 0.5 millimeters.	1	Full Compliance
PREMISES SECTIONS: s.16, s.17, s.18 (1)-(5), O. Reg. 67/93	1	Full Compliance
VENTILATION SECTIONS: S.19 (1)-(5), S.20 (1)-(3), O. Reg. 67/93	1	Full Compliance
HEATING SECTION: S.21 (1)-(3), O. Reg. 67/93	1	Full Compliance
LIGHTING SECTIONS: s.22 (1)-(3), s.23, s.24, s.25, s.26, s.27, O. Reg. 67/93	1	Full Compliance

2006 REPORT OF THE GENERAL MANAGER
OCCUPATIONAL HEALTH & SAFETY ACT HEALTH CARE & RESIDENTIAL FACILITIES
LOCATION(S): NEWMARKET HEALTH CENTRE MAPLE HEALTH CENTRE

STATUS REPORT RATING SCALE:

1 = Compliant
2 = Partially Compliant
3 = Not Compliant
4 = Not Applicable

REGULATION	COMPLIANCE STATUS	COMMENTS, ACTION TAKEN AND/OR FOLLOW-UP ACTIVITIES PLANNED
HYGIENE FACILITIES SECTIONS: s.28, s.29 (1)-(2), s.30, s.32, O. Reg. 67/93	1	Full Compliance
WORK SURFACES SECTIONS: s.33 (1)-(4), s.34 (1)-(2), s.35, s.36 (1)-(2), s.37, s.38, s.39, s.40, s.41 (1)-(2) O. Reg.67/93	1	Full Compliance
RESTRICTED SPACES SECTIONS: 42 (1)-(3) O. Reg. 67/93,	1	Full Compliance
CONFINED SPACES SECTIONS: 43 (1)-(8) O. Reg. 67/93, s.43.	1	Sewer lines/manholes are serviced by a contracted company eliminating the need for staff to enter a confined space. Contract service specifications require that the Contractor and his/her staff comply with this legislation.
EQUIPMENT SECTIONS: s.44, s.45, s.46, s.47, s.48, s.49 (1)-(2), s.50 (1)-(2), s.51, s.52 (1)-(3), s.53, s.54, s.55, s.57, s.58, s.59 (1)-(6), s.60 (1)-(2), O. Reg.67/93	1	Full Compliance
SECTIONS: s.56, s.59, O. Reg. 67/93	4	Refers to equipment used in a laboratory. All lab services are provided under contract off-site.
ELECTRICAL EQUIPMENT SECTIONS: s.62, s.63, s.64, s.65, s.66 (1)-(5), s.67, O. Reg.67/93	1	Full Compliance
s.68 (1)-(6), s.69, s.70 (1)-(2), s.71, (1)-(2), s.72, s.73 O. Reg. 67/93	4	All power lines on site are buried underground.
COMPRESSED GAS CYLINDERS SECTION: 74 (1)-(4) O. Reg. 67/93	1	Full Compliance
MATERIAL HANDLING EQUIPMENT SECTIONS: s.75, s.76(1)-(7), s.77, s.78, s.79 (1)-(7) O. Reg.67/93	1	Full Compliance
LADDERS SECTIONS: s.80 (1)-(2), s.81, s.82 (1)-(2), s.83, s.84 (1)-(2) O. Reg. 67/93	1	Full Compliance
SCAFFOLDS SECTIONS: s.85, s.86, s.87 (1)-(3), s.88 (1)-(2), s.89, s.90, O. Reg. 67/93	1	Full Compliance

2006 REPORT OF THE GENERAL MANAGER
OCCUPATIONAL HEALTH & SAFETY ACT HEALTH CARE & RESIDENTIAL FACILITIES
LOCATION(S): NEWMARKET HEALTH CENTRE MAPLE HEALTH CENTRE

Page 3 of 3

STATUS REPORT RATING SCALE:

1 = Compliant
2 = Partially Compliant
3 = Not Compliant
4 = Not Applicable

REGULATION	COMPLIANCE STATUS	COMMENTS, ACTION TAKEN AND/OR FOLLOW-UP ACTIVITIES PLANNED
SUSPENDED SCAFFOLDS SECTIONS: s.91 (1)-(6), s.92 (1)-(2), s.93 (1)-(5) O. Reg. 67/93, s.94 (1)-(3) O. Reg. 67/93	4	Suspended scaffold equipment is not utilized in the centres.
EXPLOSIVE HAZARDS SECTIONS: s.95 O. Reg. 67/93	1	Full Compliance
ANAESTHETIC GASES SECTION: 96 (1)-(5) o. Reg. 67/93, s.96	4	Antineoplastic drugs are not administered in the centres.
ANTINEOPLASTIC DRUGS SECTIONS: S.97 (1)-(3) o. Reg. 67/93	1	Full Compliance
FLAMMABLE LIQUIDS SECTIONS: s.98, s.99 (1)-(3), s.100 (1)-(3), s.101 (1)-(3), s.102 (1)-(3), O. Reg. 67/93	1	Full Compliance
MATERIALS HANDLING SECTIONS: s.103 (1)-(2), s.104, s.105, s.106, s.107, s.108, O. Reg. 67/93 s.109 (1)-(2) Concerns in-house laboratory services. s.100 O. Reg. 67/93	1 4 1	Full Compliance All laboratory services are provided under contract off-site. Full Compliance
HOUSEKEEPING AND WASTE SECTIONS: s.111 (1)-(2), s.112, s.113 (1)-(2), s.114 (1)-(3), s.115, s.116 (1)-(3) O. Reg. 67/93	1	Full Compliance